

GOLDAIR

Kitchen Scale

Model GKS200

OPERATING INSTRUCTIONS



Thank you for choosing GOLDAIR kitchen scales. This GOLDAIR appliance has been designed and manufactured to high standards of engineering and with proper use and care, as described in this leaflet, will give you years of useful service. Please read these instructions carefully.

GENERAL CARE AND SAFETY GUIDE

Please read all instructions carefully before using this appliance and keep them for future reference.

SPECIFICATIONS

Equipped with a high precision strain-gauge sensor

Capacity: 3kg

Measurement increments: 1g

Automatic zero resetting

Overload indicator "EEEE"

Low power indicator

Automatic switch off

Tare Function

Two modes (g/oz)

Power supply: lithium battery included - 1 x 3V CR2032

OPERATING YOUR SCALE

1. Put the kitchen scale on a hard & flat surface.
2. Press the "ON/OFF" button, and wait approximately 3 seconds for the scale to reset to zero.
3. Place the object to be weighed into the glass platform, the weight will appear on the display.



TARE FUNCTION

- The Tare function can be used to weigh different ingredients into the same container.
- When weighing different ingredients into the same container measure the first ingredient, press the "TARE" button to reset the display to zero and add the next ingredient to the container. The weight of only the second ingredient will be displayed.



SWITCH OFF

- Once finished with the scale, press the “ON/OFF” button to turn off.
- The scale will automatically turn itself off if not used for approximately one minute.

MEASUREMENT UNITS (g/oz)

Press the “MODE” button to alternate between grams and ounces.



OVERLOAD INDICATOR

When the scale is overloaded (3kg) the following will appear on the screen “EEEE”



CARE AND CLEANING

- Place your scale on a hard and flat surface for an accurate and reliable result.
- Uneven surfaces may affect readings.
- Clean your scale with a damp cloth. DO NOT allow water to get inside the scale.
- DO NOT use chemical abrasive cleaners to clean the scale.
- DO NOT saturate your scale with water, as this can damage the electronics.
- DO NOT store the scale in an upright position when not in use as this will drain the battery.
- If the scale will not be used for a long period of time, remove the battery.
- Do not drop or jump on your scale.

Goldair
11 Jipcho Road, Sockburn
P.O. Box 6153, Upper Riccarton
Christchurch, New Zealand
Phone 03 963 7460, Fax 0800 964 964
Email: goldair@ssm-nz.com

GOLDAIR